

# COSSES EN CUIVRE

## COPPER LUGS

COSSES EN CUIVRE		Grosueur du cable Cable size	Diamètre du trou Hole diameter
COPPER LUGS			
	Q-105015-010	8	#10
	Q-105016-010	8	1/4
	Q-105017-010	8	5/16
	Q-105018-010	8	3/8
	Q-105019-010	8	1/2
	Q-105035-010	6	#10
	Q-105036-010	6	1/4
	Q-105037-010	6	5/16
	Q-105038-010	6	3/8
	Q-105039-010	6	1/2
	Q-105056-010	4	1/4
	Q-105057-010	4	5/16
	Q-105058-010	4	3/8
	Q-105059-010	4	1/2
	Q-105076-010	2	1/4
	Q-105077-010	2	5/16
	Q-105078-010	2	3/8
	Q-105079-010	2	1/2
	Q-105096-010	1	1/4
	Q-105097-010	1	5/16
	Q-105098-010	1	3/8
	Q-105099-010	1	1/2
	Q-105116-010	1/0	1/4
	Q-105117-010	1/0	5/16
	Q-105118-010	1/0	3/8
	Q-105119-010	1/0	1/2
	Q-105136-010	2/0	1/4
	Q-105137-010	2/0	5/16
	Q-105138-010	2/0	3/8
	Q-105139-010	2/0	1/2
	Q-105156-010	3/0	1/4
	Q-105157-010	3/0	5/16
	Q-105158-010	3/0	3/8
	Q-105159-010	3/0	1/2
	Q-105176-010	4/0	1/4
	Q-105177-010	4/0	5/16
	Q-105178-010	4/0	3/8
	Q-105179-010	4/0	1/2

