

# CHARTE DES FILETS MÉTRIQUES

## BASIC METRIC THREAD CHART

### M1-M100

Diamètre	Gros filet	Filet fin		
<i>Diameter</i>	<i>Coarse pitch</i>	<i>Fine thread pitches</i>		
M1	0.25	0.2		
M1.2	0.25	0.2		
M1.4	0.3	0.2		
M1.6	0.35	0.2		
M1.7	0.35			
M1.8	0.35	0.2		
M2	0.4	0.25		
M2.2	0.45	0.25		
M2.3	0.4			
M2.5	0.45	0.35		
M2.6	0.45			
M3	0.5	0.35		
M3.5	0.6	0.35		
M4	0.7	0.5		
M5	0.8	0.5		
M6	1	0.75		
M7	1	0.75		
M8	1.25	1	0.75	
M9	1.25	1	0.75	
M10	1.5	1.25	1	0.75
M11	1.5	1	0.75	
M12	1.75	1.5	1.25	1
M14	2	1.5	1.25	1
M16	2	1.5	1	
M18	2.5	2	1.5	1
M20	2.5	2	1.5	1
M22	2.5	2	1.5	1
M24	3	2	1.5	1
M27	3	2	1.5	1
M30	3.5	3	2	1.5
M33	3.5	3	2	1.5
M36	4	3	2	1.5
M39	4	3	2	1.5
M42	4.5	4	3	2
M45	4.5	4	3	2
M48	5	4	3	2
M52	5	4	3	2
M56	5.5	4	3	2
M60	5.5	4	3	2
M64	6	4	3	2
M68	6	4	3	2
M72	6	4	3	2
M80	6	4	3	2
M90	6	4	3	2
M100	6	4	3	2