




VIS MÉCANIQUE TÊTE PAN PRISE CARRÉ ACIER ZINC

MACHINE SCREW PAN SOCKET ZINC PLATED

#6 - #8 - #10 - #12 - #14

FINI/FINISH : Acier zinc / Zinc plated

PAGE 1/2

| VIS MÉCANIQUE TÊTE PAN PRISE CARRÉ ACIER ZINC MACHINE SCREWS PAN SOCKET ZINC PLATED | DIAMÈTRE DIAMETER | GRANDEUR SIZE | |
|--|----------------------|------------------|-------|
|  | V-PSMS-440014 | 4-40 | 1/4 |
| | V-PSMS-440038 | 4-40 | 3/8 |
| | V-PSMS-440012 | 4-40 | 1/2 |
| | V-PSMS-440034 | 4-40 | 3/4 |
| | V-PSMS-440100 | 4-40 | 1 |
| | V-PSMS-632014 | 6-32 | 1/4 |
| | V-PSMS-632038 | 6-32 | 3/8 |
| | V-PSMS-632012 | 6-32 | 1/2 |
| | V-PSMS-632034 | 6-32 | 3/4 |
| | V-PSMS-632100 | 6-32 | 1 |
| | V-PSMS-632114 | 6-32 | 1.1/4 |
| | V-PSMS-632112 | 6-32 | 1.1/2 |
|  | V-PSMS-832014 | 8-32 | 1/4 |
| | V-PSMS-8320516 | 8-32 | 5/16 |
| | V-PSMS-832038 | 8-32 | 3/8 |
| | V-PSMS-832012 | 8-32 | 1/2 |
| | V-PSMS-832058 | 8-32 | 5/8 |
| | V-PSMS-832034 | 8-32 | 3/4 |
| | V-PSMS-832100 | 8-32 | 1 |
| | V-PSMS-832114 | 8-32 | 1.1/4 |
| | V-PSMS-832112 | 8-32 | 1.1/2 |
| | V-PSMS-832134 | 8-32 | 1.3/4 |
| | V-PSMS-832200 | 8-32 | 2 |
| | V-PSMS-832212 | 8-32 | 2.1/2 |
|  | V-PSMS-832300 | 8-32 | 3 |
| | V-PSMS-1024014 | 10-24 | 1/4 |
| | V-PSMS-1024038 | 10-24 | 3/8 |
| | V-PSMS-1024012 | 10-24 | 1/2 |
| | V-PSMS-1024058 | 10-24 | 5/8 |
| | V-PSMS-1024034 | 10-24 | 3/4 |
| | V-PSMS-1024100 | 10-24 | 1 |
| | V-PSMS-1024114 | 10-24 | 1.1/4 |
| | V-PSMS-1024112 | 10-24 | 1.1/2 |
| | V-PSMS-1024134 | 10-24 | 1.3/4 |
| | V-PSMS-1024200 | 10-24 | 2 |
| | V-PSMS-1024212 | 10-24 | 2.1/2 |
| | V-PSMS-1024300 | 10-24 | 3 |
| | V-PSMS-1024312 | 10-24 | 3.1/2 |
| | V-PSMS-1024400 | 10-24 | 4 |


VIS MÉCANIQUE TÊTE PAN PRISE CARRÉ ACIER ZINC

MACHINE SCREW PAN SOCKET ZINC PLATED

#6 - #8 - #10 - #12 - #14

FINI/FINISH : Acier zinc / Zinc plated

PAGE 2/2

| VIS MÉCANIQUE TÊTE PAN PRISE CARRÉ ACIER ZINC MACHINE SCREWS PAN SOCKET ZINC PLATED | DIAMÈTRE DIAMETER | GRANDEUR SIZE | |
|--|----------------------|------------------|-------|
|  | V-PSMS-1032014 | 10-32 | 1/4 |
| | V-PSMS-1032038 | 10-32 | 3/8 |
| | V-PSMS-1032012 | 10-32 | 1/2 |
| | V-PSMS-1032058 | 10-32 | 5/8 |
| | V-PSMS-1032034 | 10-32 | 3/4 |
| | V-PSMS-1032100 | 10-32 | 1 |
| | V-PSMS-1032114 | 10-32 | 1.1/4 |
| | V-PSMS-1032112 | 10-32 | 1.1/2 |
| | V-PSMS-1032134 | 10-32 | 1.3/4 |
| | V-PSMS-1032200 | 10-32 | 2 |
| | V-PSMS-1032212 | 10-32 | 2.1/2 |
| | V-PSMS-1032300 | 10-32 | 3 |
| | V-PSMS-1224012 | 12-24 | 1/2 |
| | V-PSMS-1224034 | 12-24 | 3/4 |
| | V-PSMS-1224100 | 12-24 | 1 |
| | V-PSMS-1224112 | 12-24 | 1.1/2 |
| | V-PSMS-14038 | 1/4-20 | 3/8 |
| | V-PSMS-14012 | 1/4-20 | 1/2 |
| | V-PSMS-14058 | 1/4-20 | 5/8 |
| | V-PSMS-14034 | 1/4-20 | 3/4 |
| | V-PSMS-14100 | 1/4-20 | 1 |
| | V-PSMS-14114 | 1/4-20 | 1.1/4 |
| | V-PSMS-14112 | 1/4-20 | 1.1/2 |
| | V-PSMS-14134 | 1/4-20 | 1.3/4 |
| | V-PSMS-14200 | 1/4-20 | 2 |
| | V-PSMS-14212 | 1/4-20 | 2.1/2 |
| | V-PSMS-14300 | 1/4-20 | 3 |